

Figure 1: Site Map





Figure 2: Entrance of proposed access as viewed from entrance to existing access



Figure 3: View of secondary access road from Toro Canyon Road. Staff used Google Streetview to show the area in 2012 and compare the area with site visit photos from 2015. A comparison of the photos shows vegetation before and after the unpermitted grading.



Figure 4: Photo of chopped down oak tree provided by appellants



Figure 5: Photo of appellants' former biologist showing P&D staff where an oak tree was chopped down




Figure 6: Photo of native plant debris adjacent to unpermitted secondary access road



Figure 7.a: Photo of area pre-disturbance in December 2013. Source: Google Earth



Figure 7.b: Photo of area pre-disturbance in August 2012. Source: Google Earth





Figure 7.c: Photo of area pre-disturbance in April 2013. Source: Google Earth



Figure 8.a: Photo of area of disturbance in May 2015. Source: Google Earth



Figure 8.b: Photo of area of disturbance in February 2016. Source: Google Earth



Figure 9: Photo of unpermitted grading adjacent to Toro Canyon Creek



Figure 10: Photo of area of disturbance and boulders placed by appellants within Toro Canyon Creek



Figure 11: Photo of area of disturbance



Figure 12: Photo of boulders placed within Toro Canyon Creek provided by appellants



Figure 13: Photo of area of disturbance





Figure 14: Photo of area of disturbance



Figure 15: Photo of boulders placed within Toro Canyon Creek by appellants



Figure 16: Photo of boulders placed by appellants adjacent to creek and around trunk of an oak tree