



**View looking west at Hollister Ranch Road.**



**Portion of Hollister Ranch Road undermined by January rains to the east of existing culvert crossing.**



**Initial emergency repair performed to stop water undermining road (to be removed as part of this project). Void in Hollister Ranch Road was filled with native material and angular rock at the exposed edge created by the flood waters. Bags of Quikrete concrete were placed between top of rip rap and bottom of road for added stability.**



**View looking downstream (south) at Santa Anita Creek existing culvert crossing.**



**View looking upstream (north) at previous at grade concrete crossing and failed bottomless arch corrugated metal pipe culvert.**