



Legislation Details (With Text)

File #: 23-00685 **Version**: 1

Type: Administrative Item Status: Agenda Ready

File created: 6/30/2023 In control: BOARD OF SUPERVISORS

On agenda: 7/11/2023 Final action: 7/11/2023

Title: Consider recommendations regarding a report on Case No. 23EMP-00010: Caltrans Gaviota Scour

Repair and Wall, between post miles 47.1 and 47.74, near the Gaviota Tunnel, Gaviota area, Third

District, as follows:

a) Receive and file the report on Emergency Permit Case No. 23EMP-00010, approved by the Director of Planning and Development on May 30, 2023, which authorized the construction of an approximately 550-foot-long secant pile wall and installation of Rock Slope Protection (RSP) to repair the revetment and embankment supporting southbound Highway 101 just South of the Gaviota Tunnel, between Post Miles 47.1 and 47.25, and repair of three spot locations of scour damage between Post Miles 47.25 to 47.75; and

b) Determine that receiving and filing this report is not a project pursuant to California Environmental Quality Act (CEQA) Guidelines Section 15378(b)(5) as it is an administrative government activity that

will not result in direct or indirect physical changes in the environment.

Sponsors: PLANNING AND DEVELOPMENT DEPARTMENT

Indexes:

Code sections:

Attachments: 1. Board Letter, 2. Attachment 1 - Emergency Permit 23EMP-00010, 3. Attachment 2 - CEQA Notice

of Exemption - Section 15378(b)(5), 4. Attachment 3 - CEQA Notice of Exemption - Section 15269(c),

5. Minute Order

Date	Ver.	Action By	Action	Result
7/11/2023	1	BOARD OF SUPERVISORS	Acted on as follows:	Pass

Consider recommendations regarding a report on Case No. 23EMP-00010: Caltrans Gaviota Scour Repair and Wall, between post miles 47.1 and 47.74, near the Gaviota Tunnel, Gaviota area, Third District, as follows:

- a) Receive and file the report on Emergency Permit Case No. 23EMP-00010, approved by the Director of Planning and Development on May 30, 2023, which authorized the construction of an approximately 550-footlong secant pile wall and installation of Rock Slope Protection (RSP) to repair the revetment and embankment supporting southbound Highway 101 just South of the Gaviota Tunnel, between Post Miles 47.1 and 47.25, and repair of three spot locations of scour damage between Post Miles 47.25 to 47.75; and
- b) Determine that receiving and filing this report is not a project pursuant to California Environmental Quality Act (CEQA) Guidelines Section 15378(b)(5) as it is an administrative government activity that will not result in direct or indirect physical changes in the environment.