



Lower portion of San Antonio Creek Road looking down the road east of Fee Residence. The road narrows to approximately 13 feet in width in this section. Roadside vegetation is encroaching into the travel lanes.



Lower portion of San Antonio Creek Road adjacent to eastern driveway of Fee Residence. The road is a minimum of 20 feet wide in this section. Roadside vegetation could be trimmed to maintain adequate clearance for emergency access.



Lower portion of San Antonio Creek Road adjacent to Fee Residence. The road is approximately 22 to 24 feet in width in this section. The retaining wall was constructed in 2007 to restore adequate road width.



End of San Antonio Creek Road looking towards Tucker's Grove Park. This access is controlled with flexible plastic bollards that can be driven over and signage indicating use of this access for emergency purposes.